










Quickstart - User- Manual KTS



**At the first power-on, after Installation of the control box the following steps are necessary:
(The display flashes "068")**




 Press  until the lower end position is reached.
The desk moves down with half speed. Moving up is not possible.



 Adjust the shown height with the buttons  and .



*press button  to increment the height
press button  to decrement the height
Moving up or down is not possible.*

 Press  to confirm.
After the confirmation the display flashes "088"

 Move with  to the upper limit.
You do not have to move to the absolute limit of travel.



 Adjust the shown height with the buttons  and .

*press button  to increment the height
press button  to decrement the height*

 Confirm with .

After the confirmation the height is shown and the control box is ready for normal operation.

**The following step is necessary after transport or a power fail.
(The display shows "000", until the following step is done)**

 Press  until the lower end position is reached.
The desk moves down with half speed. Moving up is not possible.

After the desk has reached the lower end position, the display shows the actual height and the control box is ready for normal operation.

Note:
The power-on settings can be preprogrammed by factory.